

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Read & Stevens, Inc.	Contact	Matt Murphy, Operations Manager
Address	PO Box 1518, Roswell, NM 88202	Telephone No.	575-622-3770
Facility Name	Bandit State #4	Facility Type	Bandit State #4 Tank Battery

Surface Owner	State	Mineral Owner	State	API No.	30-015-32553
---------------	-------	---------------	-------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	10	23S	26E	330'	North	330'	West	Eddy

Latitude _____ Longitude _____ NAD83

NATURE OF RELEASE

Type of Release	Produced H2O	Volume of Release	+/-50 bbls	Volume Recovered	+/- 48 bbls
Source of Release	Leaking nipple on heater treater	Date and Hour of Occurrence	7 am	Date and Hour of Discovery	7 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	4/17/2018	4/17/2018	
By Whom?	Kelly Barajas	Not until the next morning.	Date and Hour	4/18/2018 at 8:15 am	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
N/A					

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

The nipple on the heater treater was leaking and approximately 50 bbls of produced H2O was spilled onto location. Repairs have been made.

Describe Area Affected and Cleanup Action Taken.*

The spill was contained on the location and cleanup of the fluid was expedited in order to minimize possible future environmental impact. The contaminated soil (caliche) is being hauled to an approved disposal facility and the soil will be replaced with fresh caliche as required. New berms will be constructed around the location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *K Barajas*

Printed Name: Kelly Barajas

Approved by Environmental Specialist:

Title: Production/Regulatory

Approval Date:

Expiration Date:

E-mail Address: kbarajas@read-stevens.com

Conditions of Approval:

Attached ☐

Date: 4/18/2018

Phone: 575-624-3760

* Attach Additional Sheets If Necessary