

Received 6/26/2018

NMOCD Dist 2

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

fAB1806740738

**Release Notification and Corrective Action**

nAB1806740932

**OPERATOR**
☐ Initial Report ☒ Final Report

Name of Company Lucid Energy Delaware	Contact Kerry Egan
Address 522 W. Mermod, Ste 704, Carlsbad NM 88220	Telephone No. 575-513-8988
Facility Name Roadrunner Gas Plant	Facility Type Gas Plant

Surface Owner Lucid Energy Delaware	Mineral Owner	API No.
-------------------------------------	---------------	---------

**LOCATION OF RELEASE**

Unit Letter	Section 32	Township 23S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.26696 Longitude -104.116886 NAD83

**NATURE OF RELEASE**

Type of Release tri-ethylene glycol	Volume of Release 1000 gallons	Volume Recovered none
Source of Release Drain Valve left open on filter case	Date and Hour of Occurrence 3/4/2018 6PM	Date and Hour of Discovery 3/4/2018 7PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Amy Ruth	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The drain valve on a filter case was opened during filter change out. The valve was not closed prior to putting the filter case back into service. The TEG holding tank filled and overflowed before the valve was identified and closed. In response the pump controlling the level in the tank has been set to automatically turn preventing further overflow.

Describe Area Affected and Cleanup Action Taken.\*

The TEG affected gravel/soil in an area approximately 50' x 50'. The contaminated material has been scrapped up and disposed of at an NMOCD approved facility. Soil sampling dictated whether further excavation. See submitted closure report.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Kerry Egan	Approved by Environmental Specialist: 		
Title: Environmental Compliance Coordinator	Approval Date: 6/27/18	Expiration Date: N/A	
E-mail Address: KEgan@lucid-energy.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: 6/14/2018	Phone: 575-810-6021		<b>FINAL</b>

\* Attach Additional Sheets If Necessary

2RP-4654