

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: XTO Energy OGRID:4380	Contact: Kyle Littrell
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No: 432-221-7331
Facility Name: Sizzler Federal #2H	Facility Type: Exploration and Production

Surface Owner: State	Mineral Owner: State	API No: 30-015-44280
----------------------	----------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	6	25S	29E	180	South	1650	East	Eddy

Latitude 32.152557 Longitude -104.020787 NAD83

**NATURE OF RELEASE**


Type of Release Fresh water and chemical (scale inhibitor, PAA, biocide)	Volume of Release 450bbl water, 3 gallons chemical	Volume Recovered 449bbl water, 3 gallons chemical
Source of Release Frac tank	Date and Hour of Occurrence 7/25/2018, AM	Date and Hour of Discovery 7/25/2018, 5:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (NMOCD), Ryan Mann (SLO), Shelly Tucker (BLM)	
By Whom? Amy Ruth	Date and Hour: 7/25/2018, 1:54 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Frac tank overflowed during filling. Valves were closed and flow to tank was stopped.

Describe Area Affected and Cleanup Action Taken.\*  
Fluid was released into lined containment. Less than one barrel escaped through a hole in the liner. Vacuum truck was dispatched and recovered all fluid from containment. The breach in the liner was patched and containment was cleaned. An environmental contractor has been retained to assist with remediation efforts.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy C. Ruth	Approved by Environmental Specialist: Maria Pruett	
Title: Environmental Coordinator	Approval Date: 08/11/18	Expiration Date: N/A
E-mail Address: Amy_Ruth@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Rev 8/10/2018 Phone: 575-689-3380		2RP-4913

\* Attach Additional Sheets If Necessary

A#: pMAP1822337557  
I#: nMAP1822337753