

Location:	PLU 23 DTD 108H (30-015-42452)	
Spill Date:	2/13/2019	
Length of Spill=	497.00	feet
Width of Spill=	15.00	feet
Saturation (or depth) of Spill=	9.00	inches
Approximate Oil %	-	
Porosity Factor=	0.15	
Volume Recovered=	-	bbls

VOLUME OF LEAK		
Total Oil=	-	barrels
Total Produced Water=	149	barrels

VOLUME RECOVERED		
Total Oil=	-	barrels
Total Produced Water=	-	barrels