Venegas, Victoria, EMNRD

From: Baker, Larry <Larry.Baker@apachecorp.com>

Sent: Friday, March 27, 2020 8:37 AM **To:** Venegas, Victoria, EMNRD

Subject: [EXT] RE: Ghost Rider 22-15 Fed COM 202# 1RP-5635

Ms. Venegas,

I checked the API number on the C-141 and it is wrong. The API number for this release is 30-025-45769. Let me know if I need to do something on my end. Sorry for the inconvenience. Thanks and have a good day.

BRUCE BAKER

ENVIRONMENTAL TECHNICIAN SR direct 575-393-7106 ext 1523 | Cell 432-631-6982 APACHE CORPORATION 2350 W. MARLAND BLVD HOBBS, NM 88240

ApacheCorp.com | LinkedIn | Facebook | Twitter | StockTwits | YouTube

From: Venegas, Victoria, EMNRD [mailto:Victoria.Venegas@state.nm.us]

Sent: Wednesday, March 25, 2020 1:01 PM **To:** Baker, Larry < Larry.Baker@apachecorp.com>

Subject: [EXTERNAL] RE: Ghost Rider 22-15 Fed COM 202# 1RP-5635

Mr. Baker,

Sorry, but the lat/log in the closure report and in the C-141 do not match the API# provided in the initial C-141. Can you please check the initial C-141 and let me know if the API# is wrong? I need to update the system and make the necessary corrections if the API# is incorrect.

Thanks again,

Victoria Venegas
State of New Mexico
Energy, Minerals, and Natural Resources
Oil Conservation Division
811 S. First St., Artesia NM 88210
(575) 748-1283
Victoria.Venegas@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: Venegas, Victoria, EMNRD

Sent: Wednesday, March 25, 2020 11:34 AM

To: Baker, Larry < Larry.Baker@apachecorp.com >

Subject: Ghost Rider 22-15 Fed COM 202# 1RP-5635

Sorry, I'm asking for the closure Report for Ghost Rider 22-15 Fed COM 202# 1RP-5635

From: Venegas, Victoria, EMNRD

Sent: Wednesday, March 25, 2020 9:51 AM **To:** Baker, Larry < <u>Larry.Baker@apachecorp.com</u>>

Subject: NDHR1922134717 EAST BLINEBRY DRINKARD UNIT #037 @ 30-025-06556

Closure Report NDHR1922134717 EAST BLINEBRY DRINKARD UNIT #037 @ 30-025-06556

Good morning Mr. Baker,

Can you please clarify the following: Where is sample point SP3 located on the confirmation sampling map (Bottom Samples Grid)? The report says the SP3 sample was excavated @ 1foot. Final Bottom Samples Table shows the results for samples that were taken at the surface and sample B26 was collected @6".

On page 16, what does GR202H stands for?

Thanks,

Victoria Venegas State of New Mexico Energy, Minerals, and Natural Resources Oil Conservation Division 811 S. First St., Artesia NM 88210 (575) 748-1283 Victoria.Venegas@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

WARNING EXTERNAL EMAIL: This email is from an external source. Do not click links or open attachments without positive sender verification of purpose. Never enter Username, Password or sensitive information on linked pages from this email. If you are unsure about the message, please contact the Apache IT ServiceDesk for assistance.