

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Thursday, May 7, 2020 9:36 AM
To: 'Rob Kirk'; Hamlet, Robert, EMNRD; Bratcher, Mike, EMNRD; Eads, Cristina, EMNRD
Cc: CFO_Spill, BLM_NM; Guesnier, Joseph R
Subject: NDHR1918948878 CAZA EAGLE CLAW LINE @ FDHR1918948760 1RP-5609
Attachments: (C-141 Remediation Plan) NDHR1918948878 CAZA EAGLE CLAW LINE @ FDHR1918948760 1RP-5609.pdf

NDHR1918948878 CAZA EAGLE CLAW LINE @ FDHR1918948760 1RP-5609

Mr. Kirk,

The OCD has approved the Site Characterization and Remediation Plan for incident # NDHR1918948878 CAZA EAGLE CLAW LINE @ FDHR1918948760 1RP-5609 with the following conditions of approval:

- The entire spill area, including the lease road, must meet the 4 foot reclamation standard. Once the top 4 feet are clean and based on data already obtained, a liner installation will not be necessary for this site.

The signed C-141 can be found in the online image data base under the incident #.

Thank you,

Victoria Venegas
State of New Mexico
Energy, Minerals, and Natural Resources
Oil Conservation Division
811 S. First St., Artesia NM 88210
(575) 748-1283
Victoria.Venegas@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.