Page 19 of 228

Incident ID	NRM2002733872
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following i	tems must be included in the closure report.	
 ✓ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection) ✓ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling) 		
		✓ Description of remediation activities
and regulations all operators are required to report and/or file certai may endanger public health or the environment. The acceptance of should their operations have failed to adequately investigate and replacement human health or the environment. In addition, OCD acceptance of	ations. The responsible party acknowledges they must substantially onditions that existed prior to the release or their final land use in	
Signature:	Date: 5/26/2020	
email: itavarez@concho.com	Telephone: (432) 701 8630	
OCD Only		
Received by: Victoria Venegas	Date: 05/27/2020	
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.	
Closure Approved by:	Date: <u>07/13/2020</u>	
Printed Name: Victoria Venegas	Title: Engineering Tech. III	