

From: [Blaney, Karolina](#)
To: ["Tucker, Shelly"](#)
Cc: [Pruett, Maria, EMNRD](#); [Raley, Jim](#)
Subject: [EXT] RE: WPX - header spill - Initial C-141
Date: Monday, October 8, 2018 12:29:09 PM
Attachments: [NM Main Header - C-141 Initial.docx](#)

Good afternoon,
Attached is the initial C-141 form for the NM Main Header spill.
Please let me know if you have any questions or concerns.
Thank you,

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com

From: Blaney, Karolina
Sent: Wednesday, September 26, 2018 1:27 PM
To: Tucker, Shelly <stucker@blm.gov>
Cc: 'Pruett, Maria, EMNRD' <Maria.Pruett@state.nm.us>; Raley, Jim <james.ralej@wpxenergy.com>
Subject: WPX - header spill - excavation permission

Good afternoon Shelly,

WPX had a spill yesterday, 9-25-19, at the NM main header. The spill was caused by corrosion; approximately 8 bbls of fluids spilled on the pipeline ROW and a very small volume migrated onto the stateline road. We placed the one call this morning to excavate the impacts. The spill is entirely contained within previously disturbed area however, I'd like to ask for your permission to excavate it. The coordinates of the spill are 32.00647, -103.87806 (see my homemade map below). There is an arc area to the west of it but, as mentioned above, the spill is entirely contained within previously disturbed area outside of the arc area.

We would like to start the excavation activities as soon as the lines are located. Please let me know if you have any questions.

Thank you,

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com

