



Devon Energy Production Company, LP

Request for Incident Closure

June 5th, 2020

Caprock 27 St Fed Com #1H

API – 30-025-41148

nCH1819853444

NO-RP

Description of Original Incident:

On July 2nd of 2018, a Victaulic clamp on the water load line developed a leak, which caused fluid to be released into the lined secondary containment. The release was all produced water and was approximately 10 bbls in volume. All fluid was recovered from containment. The location of this site is, N-27-18S-34E; 32.7126541, -103.5503769.

Immediate Actions Taken:

A vacuum truck was called out to recover the fluid inside containment and the Victaulic clamp was replaced. As you can see in the following photos, the liner integrity remains intact.

Our current assessment of this incident was performed on June 3rd, 2020. **With the information and pictures provided, we would like to respectfully request that the incident be closed out.**

Thank you so much for your time. If there is anything more that you would like us to do with this incident in order to close it out, please let us know and we'll be happy to make the necessary arrangements.

Have a wonderful day,

Tom Bynum

Tom Bynum

EHS Consultant/Contractor

tom.bynum@devon.com

580-748-1613



Devon Energy Production Company, LP





Devon Energy Production Company, LP





Devon Energy Production Company, LP





Devon Energy Production Company, LP





Devon Energy Production Company, LP



District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nCH1819853444
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: *Each of the following items must be included in the closure report.*

- ☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☒ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☐ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Tom Bynum Title: EHS Consultant

Signature: Tom Bynum Date: 6/5/2020

email: tom.bynum@dvn.com Telephone: 575-748-0176

Incident ID	nCH1819853444
District RP	NO-RP
Facility ID	
Application ID	

OCD Only

Received by: _____ Date: _____

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: _____ Date: _____

Printed Name: _____ Title: _____