

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised June 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-25851
Release Notification and Corrective Action

OPERATOR

☐ Initial Report

☒ Final Report

Name of Company: MCELVAIN Oil and Gas Properties Inc.	Contact: George Broome or Clayton M Barnhill
Address: PO Box 2148 Santa Fe, NM 87504	Telephone No. 505-757-3995 CMB: 505-626-1615
Facility Name: Parcell Federal 002	Facility Type: Producing Well
Surface Owner: USA	Mineral Owner: USA
Lease No. 30-015-25851-00-00	

LOCATION OF RELEASE

Unit Letter E	Section 31	Township 18 South	Range 30 East	Feet from the 2310'	North/South Line North Line	Feet from the 1593'	East/West Line West Line	County: Eddy County, New Mexico
------------------	---------------	----------------------	---------------------	------------------------	--------------------------------	------------------------	-----------------------------	------------------------------------

NATURE OF RELEASE


Type of Release: Hydrocarbon Release from flow line of tank battery.	Volume of Release: Unknown	Volume Recovered: None
Source of Release: Pump Jack	Date and Hour of Occurrence	Date and Hour of Discovery Unknown
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*: Heavy Contamination at wellhead and area 25' x 25' feet that has been covered. Pile of contaminated soil on location. NMOCD Site Inspection/ Inspection No: iMLB0317038786 06/19/03 performed by Mike Bratcher, NMOCD District II Office.

Describe Area Affected and Cleanup Action Taken. * Area affected is around wellhead, and pile of previously removed soil. Site inspection made with Mike Stubblefield of the OCD Artesia District II Office, phone (505) 748-1283, on Monday 07/15/03 at 11:00 hour. At this site inspection, it was determined the operator should clean up the impacted soil around the wellhead by removing the soil until TPH concentrations are below 5000 PPM TPH, and replace with clean soil. Existing Pile of contaminated Soil, and soil removed from around the pad location on 03/17/2004 by Gandy Marley Inc. and transported to their offsite commercial landfarm. Clean soil was added.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Clayton M Barnhill		TIM W. GUM DISTRICT I SUPERVISOR	
Title: Agent		Approval Date: 4/28/2004	Expiration Date:
E-mail Address: cmbenviro@dfn.com or broome@pecos-nm.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date 04/23/04	Phone: 505-626-1615		

* Attach Additional Sheets If Necessary