District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

Form C-144

June 1, 2004

Pit or Below-Grade Tank Registration or Closure
Is pit or below-grade tank covered by a "general plan"? Yes No \(\sqrt{1} \)

Type of action: Registration of a pit or below-grade tank Closure of a pit or below-grade tank		
Operator:DEVON ENERGY PRODUCTION CO., LPTelephone Address:PO Box 250 Artesia, NM 88211 Facility or well name: Todd 15 J Fed 10API #: 30.01 S County:Edd yLatitudeLongitude	5 · 33/06 U/L or Qtr/Qtr J Sec /5 Ta	23S R 31 E
Pit Type: Drilling ⊠ Production ☐ Disposal ☐ Workover ☐ Emergency ☐ Lined ⊠ Unlined ☐ Liner type: Synthetic ⊠ Thickness 12 mil Clay ☐ Pit Volumebbl	Below-grade tank Volume:bbl Type of fluid: Construction material: RECEIVED Double-walled, with leak detection? Yes	
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) (10 points) (0 points)
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) (0 points)
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) (0 points)
If this is a pit closure: (1) attach a diagram of the facility showing the pit's your are burying in place) onsite offsite foffsite, name of facility remediation start date and end date. (4) Groundwater encountered: No Y Attach soil sample results and a diagram of sample locations and excavations	(3) Attach a general	description of remedial action taken including
AUG 0 5 2004		
	OCD-A	RTESIA
I hereby certify that the information above is true and complete to the best of been/will be constructed or closed according to NMOCD guidelines, and the	signature Signature Signature trelieve the operator of liability should the contents	of the pivor tank contaminate ground water or
Approval: Printed Name/Title	Signature	Date: AUG 6 2004