Form 3160-5 (September 2001)

UNITED STATES V.M. OII Cons. DIV-DIST. 2 DEPARTMENT OF THE INTERIOR W. Grand Avenue BUREAU OF LAND MANAGEMENT W. Grand Avenue

FORM APPROVED OMB No. 1004-0135

SUNDRY NOTICES AND REPORTS AND SIE, NM 88210

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Expires January 31, 2004 5. Lease Serial No.

abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on rever					7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Oil Well Gas	Well Gas Well X Other P&A AUG 0 5 2004 OCD-ARTESIA				8. Well Name and No.	
2. Name of Operator					Biplane Unit Com #4	
Yates Petroleum Corporation					9. API Well No.	
3a. Address 3b. Phone No. (include area code)					30-005-6020	
105 S. 4th Str., Artesia, NM 8	505	505-748-1471		10. Field and Pool, or Exploratory Area Haystack Cisco		
4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)					11. County or Parish, State	
CCOURNIL 8 4000/EVALL of Continue 45 TGC POZE (Limit C. NIENIA)					· ·	
660'FNL & 1980'FWL of Section 15-T6S-R27E (Unit C, NENW)				TOTICE DE	Chaves County, New Mexico	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RE						
TYPE OF SUBMISSION TYPE OF ACTION						
Notice of Intent	Acidize Alter Casing Casing Repair	=	en ure Treat Construction	Production Reclamation	(Start/Resume)	Water Shut-Off Well Integrity Other
Subsequent Report	Change Plans	X Phus	and Abandon	Temporarily	Abandan	
Final Abandonment Notice				Water Dispo		
testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 7/1/04-7/29/04 Replaced 14' of bad 8-5/8" casing and installed flange. Dumped 8 yds of redi-mix around 8-5/8" casing and installed cellar. TIH with 7-7/8" mill tooth bit. Drilled cement from 12' to 28'. Fell out of cement. Lost circulation at 28'. Pumped 430 bbls brine at 5 BPM (would not circulate). TIH and tagged at 1430'. Pumped 95 bbls fluid down annulus with no pressure increase. Pumped 40 bbls down tubing. Drilled cement or bridge from 1430' to 1441'. Drilled and circulated down from 1441' to top of 5-1/2" casing at 2484'. NOTE: No circulation to surface. Tagged cement in top of 5-1/2" casing at 2484'. Drilled 4' cement in top of 5-1/2" casing. Fell out of cement. Pushed casing downhole from 2484'-2667'. Cut 2' from 2667' to 2669'. Tagged at 2669'. Spear into 5-1/2" casing. Did not catch fish. Could not find any casing below overshot. Spot 400' plug from 2700' up to 2300'. Waited 2 hrs and tagged plug at 2072'. Spot 100' plug 50' below 8-5/8" casing and and 50' inside. Waited 2 hrs. Weight to tag, plug was not there. Re-spot plug at 1400' and POOH. Tagged plug at 1390'. Spot 30 sx plug in 16de 8-5/8" casing. Set 10 sx surface plug. Installed dry hole marker. WELL IS PLUGGED AND ABANDONED. FINAL REPORT.						
inspector on location to confirm all reclamation requirements before receiving the notice of written order.						
14. I hereby certify that the foregoing is true and Name (Printed/Typed) Tina Huerta	Regulatory Compliance Supervisor					
Signature Jina Hurta Date August 2, 2004						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by LLL. Conditions of approval, if any, are attached. A	Title	PE	Date	8/4/64		
certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office C						