


	L 1 17S 30E	30-015-04038-00-00	015	MIT Witnessed - Bradenhead
	N 1 17S 30E	30-015-21386-00-00	030	MIT Witnessed - Bradenhead
	P 1 17S 30E	30-015-04041-00-00	019	MIT Witnessed - Bradenhead
	J 24 17S 30E	30-015-04319-00-00	023	MIT Witnessed - Bradenhead
	B 25 17S 30E	30-015-04331-00-00	011	MIT Witnessed - Bradenhead
	F 25 17S 30E	30-015-04329-00-00	009	MIT Witnessed - Bradenhead
Property	GISSLER B(A-2)			Property 15797
	L 12 17S 30E	30-015-25987-00-00	027	MIT Witnessed - Bradenhead
	F 14 17S 30E	30-015-25763-00-00	026	MIT Witnessed - Bradenhead

If you have any questions or need to reschedule any test, please contact Mr. Gerry Guye at 505-748-1283 at the Artesia district office between 7:00 am and 4:00 pm, at least two weeks prior to the indicated schedule date.

Sincerely,



Artesia OCD District Office

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

*Underground Injection Control Program
"Protecting Our Underground Sources of Drinking Water"*

22-Apr-2003

BURNETT OIL CO INC

3080

PO Box 188

Loco Hills, NM 88255

Dear Sirs:

Our records indicate that the following well(s) are due for the type of mechanical integrity test indicated. If the required test is a pressure test, please have the necessary equipment on location and ready to commence the test at the specified time. For all types of tests, please have a representative on location to operate any valves or other equipment as necessary. Your representative should meet our inspector at the **Field Office** at the date and time specified.

Scheduled Inspections / MITs

Scheduled	5/12/2003 10:00:00 AM			
	UL S-T-R	API Well No.	Well No.	Type Insp/MIT
Property	GISSLER A			Property 2388
	P 11 17S 30E	30-015-25682-00-00	012	MIT Witnessed - Bradenhead
	B 14 17S 30E	30-015-25683-00-00	013	MIT Witnessed - Bradenhead
Property	GISSLER B			Property 2389
	B 11 17S 30E	30-015-04120-00-00	007	MIT Witnessed - Bradenhead
	J 11 17S 30E	30-015-25224-00-00	018	MIT Witnessed - Bradenhead
	L 11 17S 30E	30-015-23771-00-00	016	MIT Witnessed - Bradenhead
	N 11 17S 30E	30-015-25540-00-00	022	MIT Witnessed - Bradenhead
	F 12 17S 30E	30-015-25220-00-00	021	MIT Witnessed - Bradenhead
	D 14 17S 30E	30-015-25518-00-00	023	MIT Witnessed - Bradenhead
Property	GRAYBURG JACKSON S A UNIT			Property 2390
	J 12 17S 30E	30-015-04129-00-00	037	MIT Witnessed - Bradenhead
	P 12 17S 30E	30-015-04126-00-00	035	MIT Witnessed - Bradenhead
	B 13 17S 30E	30-015-22618-00-00	045	MIT Witnessed - Bradenhead
	N 13 17S 30E	30-015-04145-00-00	013	MIT Witnessed - Bradenhead
	L 14 17S 30E	30-015-04148-00-00	022	MIT Witnessed - Bradenhead
Property	JACKSON B			Property 2391
	4 1 17S 30E	30-015-04036-00-00	004	MIT Witnessed - Bradenhead
	J 1 17S 30E	30-015-22621-00-00	032	MIT Witnessed - Bradenhead

Oil Conservation Division * 1301 W. Grand * Artesia, New Mexico 88210
Phone: 505-748-1283 * Fax: 505-748-9720 * <http://www.emnrd.state.nm.us>

**Instructions for
Preparation for MIT
Tests**

If your notification letter indicates “MIT Witnessed – Bradenhead” under the title “*Type Insp/MIT*” then the following applies:

Bradenhead test – Requires that injection pump be running and a operable pressure gauge or vacuum gauge installed on the tubing so that injection pressure may be witnessed. Does not require a pump truck. Casing & Bradenhead valves must be shut-in 24 hours prior to test. **PLEASE MAKE SURE YOU HAVE ENOUGH WATER TO RUN INJECTION PUMP ON DAY OF TEST.**

If your notification letter indicates “MIT Witnessed – Pressure test” under the title “*Type Insp/MIT*” then the following applies:

Pressure Test – Requires, in addition to the above, a pump truck capable of holding 300 psi on the casing for a period of 30 minutes. In addition a chart recorder is required with a 1000 psi capability and must have been calibrated within 12 months. Documentation of this calibration must accompany the recorder.

A company representative must be on location during the test to operate valves and equipment. Ensure company representative has seen a copy of these instructions.