Submit 3 Copies To Appropriate District Office	State of From Maries		Form C-103	
District I	Energy, Minerals and Natural Resources		May 27, 2004 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II			30-015-22242	
1301 W. Grand Ave., Artesia, NM 88210			5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 South St. Francis Dr. Santa Fe, NM 87505		STATE	FEE 🛛
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, IN	VI 87303	6. State Oil & Gas Leas	se No.
SUNDRY NOTION	7. Lease Name or Unit	Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Mitchell IN	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other SWD			8. Well Number	
RECEIVED			9. OGRID Number	
2. Name of Operator Yates Petroleum Corporation OCT 1 2 7004		9. OGRID Number 025575		
3. Address of Operator		10. Pool name or Wildcat		
105 S. 4 th Street, Artesia, N	M 88210	SON WHITE SIX	SWD - De	vonian
4. Well Location Unit Letter I : 2030 feet from the South line and 660 feet from the East line				
Section 23	Township 17S	Range 25E	NMPM Eddy	County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3476'GR Pit or Below-grade Tank Application or Closure .				
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB				
OTHER: Replace tubing & MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
·				
Repaired hole in 2-7/8" tubing and replaced 12 joints. Pressure tested 335-340 psi for 30 mins.				
See attached MIT conducted on 10/6/04 witnessed by Gerry Guy (NMOCD-Artesia).				
		•		
		Mack		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan. SIGNATURE TITLE Regulatory Compliance Supervisor DATE October 7, 2004				
SIGNATURE Jina He	TITLE I	Legulatory Compliance S	upervisor DATE	October 7, 2004
Type or print name Tina Huert			om Telephone No	
For State Use Only	•			
APPROVED BY: Conditions of Approval (if any):	TITI	.E	DAT	E
Conditions of Approval (II ally):				

