

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Woolley Tank Battery	Facility Type:	Tank Battery

Surface Owner: Federal	Mineral Owner	Lease No. (API#) NA
------------------------	---------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section 28	Township T17S	Range R30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude Longitude

NATURE OF RELEASE

Type of Release Oil	Volume of Release Oil 83 bbls	Volume Recovered Oil 80 bbls
Source of Release Failure on circulating pump	Date and Hour of Occurrence 7/23/2014 1:00 pm	Date and Hour of Discovery 7/23/2014 1:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher – OCD / Jeffery Robertson - BLM	
By Whom? Amanda Trujillo	Date and Hour 7/24/2014 4:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A failure of the circulating pump caused the release of oil. All fluid was contained within the bermed area. A vacuum truck was dispatched to removal all standing fluids.

Describe Area Affected and Cleanup Action Taken.*

The impacted area was to the south of the tanks inside the containment. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Lupe Carrasco	Approved by District Supervisor:	
Title: Environmental Coordinator	Approval Date: 8/20/2014	Expiration Date: N/A
E-mail Address: gcarrasco@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date August 15, 2014 Phone: 575-746-2010	FINAL	

* Attach Additional Sheets If Necessary

2RP-2412