

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company- Harvey E. Yates Company	Contact- Tammy R. Link
Address – P.O. Box 1933, Roswell, NM 88201-1933	Telephone No. 575-623-6601
Facility Name – Eddy JP State #1	Facility Type – Lease #NMNM073240

Surface Owner - USA	Mineral Owner- State of NM	API No. 30-015-23504
---------------------	----------------------------	----------------------

LOCATION OF RELEASE

Unit Letter N	Section 36	Township 18S	Range 31E	Feet from the 750'	North/South Line S	Feet from the 1980'	East/West Line W	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-----------------------	------------------------	---------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release – 37 bbls of oil	Volume of Release – 37 bbls	Volume Recovered -0-
Source of Release Hole in bottom of tank	Date and Hour of Occurrence 11/6/09	Date and Hour of Discovery-11/7/09 7 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher w/OCD of NM	
By Whom? Clay Stevens	Date and Hour 7:30 am 11/9/09	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


Hole in bottom of tank, will empty and clean and determine whether to repair or replace.

Describe Area Affected and Cleanup Action Taken.*

Will arrange to dig up and haul off contaminated soil and remove. See attachments of soil samples taken and reclamation complete.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist:		
Printed Name: Tammy R. Link			
Title: Engineering Tech	Approval Date: 3/31/15	Expiration Date: N/A	
E-mail Address: tlink@heycoenergy.com	Conditions of Approval: N/A FINAL		Attached <input type="checkbox"/>
Date: 1/30/15	Phone: 575-623-6601		

* Attach Additional Sheets If Necessary

2RP-685