District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Received 8/19/2015 NMOCD Artesia

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## **Release Notification and Corrective Action**

						OPERATOR			☐ Initial Report ☐ Final Repo			Final Report	
Name of Company: COG Operating LLC						Contact: Robert McNeill							
Address: 600 West Illinois Avenue, Midland TX 79701						Telephone No. 432-230-0077							
Facility Name: SRO State Unit Com #13H						Facility Type: Well							
Surface Owner: State Mineral Owner						State			API No. 30-015-37427				
				LOCA'	TION	OF REI	LEASE						
Unit Letter D	Section 15	Township 26S	Range 28E	Feet from the 660		South Line North	Feet from the 330'		West Line West		Coun	•	
Ъ	13	205				Longitude -104.082877725172				,			
NATURE OF RELEASE													
Type of Relea	ase:						Volume Recovered:						
Produced Wa	ter		20 bbls PW			15 bbls PW							
Source of Release: 4" Poly Flowline						Date and Hour of Occurrence: 3/19/2015 1:00 pm			Date and Hour of Discovery: 3/19/2015 1:00 pm				
Was Immediate Notice Given?						If YES, To Whom?							
☐ Yes ☐ No ☒ Not Required													
By Whom?						Date and Hour:							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.*  4" Poly connection on a flowline between two wells started to leak due to corrosion. Vacuum trucks were dispatched to the standing fluid and repairs were													
made.	4" Poly connection on a flowline between two wells started to leak due to corrosion. Vacuum trucks were dispatched to the standing fluid and repairs were made.												
Describe Area	a Affected a	and Cleanup A	Action Tak	en.* the posture. This re	Jancad	was addrass	ad under the guide	onas of	NMOCD no	r the energ	uad ma	rkalon	
The impacted area is approximately 40' x 20' in the pasture. This released was addressed under the guidance of NMOCD per the approved workplan.													
				is true and comple									
				d/or file certain rel e of a C-141 repor									
				investigate and rea									
or the environ	ment. In a	ddition, NMC	CD accep	tance of a C-141 re									
federal, state, or local laws and/or regulations.													
			OIL CONSERVATION DIVISION										
Signature:		1		.1									
			Approved by Environmental Specialist:										
Printed Name	: Amanda												
Title: Senior	Environme	ntal Coordinat		Approval Date: 8/20/2015			Expiration Date: N/A						
E-mail Address: atrujillo@concho.com  Date: August 18, 2015 Phone: 575-748-6940						Conditions of Approval: FINAL			Attached				
							rII						

<sup>\*</sup> Attach Additional Sheets If Necessary