

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Received 12/1/09

Release Notification and Corrective Action

Name of Company COG OPERATING LLC 229137		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address 550 W. Texas, Suite 1300 Midland, TX 79701		Contact Chasity Jackson			
Facility Name - Skelly Unit 942		Telephone No. 432-686-3087			
		Facility Type- Battery			
Surface Owner Federal		Mineral Owner		Lease No. 30-015-34645	

LOCATION OF RELEASE

Unit Letter B	Section 22	Township 17S	Range 31E	Feet from the 1210	North/South Line North	Feet from the 2195	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude

Longitude

NATURE OF RELEASE

Type of Release-Oil	Volume of Release-170bbbls	Volume Recovered- 160bbbls
Source of Release- Production tank	Date and Hour of Occurrence- 11/12/09 Approx AM	Date and Hour of Discovery 11/12/09 Approx AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Gregston BLM Mike Bratcher OCD	
By Whom? Rick Wright	Date and Hour 11/12/09 in the AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.*
A safety gauge float malfunctioned causing the production oil tank to run over. The safety gauge has been repaired.

Describe Area Affected and Cleanup Action Taken.*
The area inside the dyke has been cleaned but not backfilled. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for your approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: C Jackson		OIL CONSERVATION DIVISION	
Printed Name: Chasity Jackson		Approved by District Supervisor: Huf	
Title: Agent for COG		Approval Date: 10/5/15	Expiration Date: N/A
E-mail Address: cjackson@conchoresources.com		Conditions of Approval:	
Date: 11/17/09	Phone: 432-686-3087	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-3309

Bratcher, Mike, EMNRD

From: Kanicia Castillo [KCarrillo@conchoresources.com]
Sent: Tuesday, December 01, 2009 9:46 AM
To: Bratcher, Mike, EMNRD; terry_gregston@nm.blm.gov
Subject: Skelly Unit 942 C141
Attachments: Skelly 942 C141 111209.pdf

Mike/ Terry,

Here are the C-141's, let me know if you need anything else.

Thank you,

Kanicia Castillo

Regulatory Analyst

COG OPERATING LLC

550 W. Texas Avenue, Suite 100

Midland, Texas 79701

p.432.685.4332

f.432.685.4396



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

This inbound email has been scanned for malicious software and transmitted safely to you using Webroot Email Security.
