

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Name of Company	COG Operating LLC	Contact	Pat Ellis	<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address	550 W. Texas, Suite 1300 Midland, Texas 79701	Telephone No.	(432) 685-4332		
Facility Name	Skelly 942	Facility Type	Tank Battery		
Surface Owner	Federal	Mineral Owner		Lease No. 30-015-34645	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	22	17S	31E	1210	North	2195	East	Eddy

Latitude N 32°49.482 Longitude W 103°51.340

NATURE OF RELEASE

Type of Release Oil	Volume of Release	170 bbls	Volume Recovered	160 bbls
Source of Release	Date and Hour of Occurrence	Unknown 11/12/09 AM	Date and Hour of Discovery	11/12/09 AM
Production tank	Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
			Mike Bratcher OCD	
			Terry Gregston BLM	
By Whom? Rick Wright	Date and Hour	11/12/09 am	If YES, Volume Impacting the Watercourse.	
Was a Watercourse Reached?		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Safety gauge float malfunctioned causing the production oil tank to run over. The safety gauge has been repaired.

Describe Area Affected and Cleanup Action Taken.*

The spill was contained inside the facility firewalls. The spill area was assessed to evaluate the spill area. The impacted soils above the RRAL were removed and hauled to CRI for disposal. The excavation was backfilled with clean soil. A closure report has been prepared and submitted to the NMOCD for review and approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Ike Tavarez

Title: Project Manager

E-mail Address: ike.tavarez@tetrattech.com

Date:

Phone: (432) 682-4559

OIL CONSERVATION DIVISION

Approved by District Supervisor:

Approval Date: 10/5/15

Expiration Date: N/A

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary