

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

## Release Notification and Corrective Action

NCO					OPERA'	TOR	⊠ Initi	ial Report		Final Repor		
Name of Company COG OPERATING LLC Address 550 W. Texas, Suite 1300 Midland, TX 79701						Contact K	anicia Carrillo		ar resport		i mai Kepoi	
Facility Na	ou W. Tex	as, Suite 130	nd, TX 79701	Telephone No. 432-685-4332								
Facility Name – Skelly Unit 942						Facility Type- Battery						
Surface Ow	ner Feder	al		Mineral (	Owner				Lease 1	No. NMLC	0204	104
				1.00	ATTO	MARAR			1 Deuse 1	VO. IVIVILO	-0294	19A
Unit Letter	Section	Township	Range	Feet from the		N OF REI	· · · · · · · · · · · · · · · · · · ·					
В	I TOUR THE INC					th/South Line   Feet from the   East			West Line County Eddy			
		Latitud	e N32.	49.479'		Longitud	e W103.51	338	***************************************			
T. CD.	~~~			NAT	TURE	OF RELI	EASE					
Type of Release-Oil Source of Release- Oil tank						Volume of Release-38bbls Volume Recovered, 35bbls						
Source of Refease- Off tank							our of Occurrenc	Date and Hour of Discovery				
Was Immediate Notice Given?						12/27/09   12/27/09   If YES, To Whom?						
Yes No Not Required						Mike Bratcher OCD						
By Whom? Rick Wright						Date and Hour 12/27/09 PM						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
☐ Yes ⊠ No						, and the sounds,						
If a Watercou	rse was Imp	pacted, Descri	be Fully.*									
	lugged wat	er meter on a l	neater whi	ch then sent too r	nuch fl	uid to tank out	running the equal	izers.				
Describe Area	Affected a	nd Cleanup A	ction Take	en.*								
I hereby certify regulations all public health o should their op or the environr	y that the in operators a or the enviro- cerations ha ment. In ad	formation giver required to comment. The average failed to addition, NMOC	en above i report and ecceptance equately i	eate any possible on inificant remediati s true and complete lor file certain re of a C-141 repor nvestigate and re- unce of a C-141 re-	ete to the	ne best of my ke of the best of my ke of the best of my ke of the best of the	nowledge and un perform correcti ked as "Final Re	derstan ive actio	d that pursu ons for relea	ant to NMO ases which move the operat	CD rule	es and anger
Signature: CAUCISM						OIL CONSERVATION DIVISION						
Printed Name: Chasity Jackson A						Approved by District Supervisor:						
Title: Agent for COG						Approval Date: 10/5/15 Expiration Date: 1//1						
E-mail Address: cjackson@conchoresources.com						Conditions of Approval:						
Date: 1/7/10 attach Additio		Phone If Necessar	2: 432-686 V	5-3087						Attached [		

2RP-3310

## Bratcher, Mike, EMNRD

From:

Chasity Jackson [cjackson@conchoresources.com]

Sent:

Tuesday, January 12, 2010 8:08 AM

To:

Paul\_Evans@blm.gov; Bratcher, Mike, EMNRD; James\_Amos@blm.gov

Cc:

Pat Ellis; Kanicia Castillo

Subject:

Skelly Unit #975 C-141, Skelly Unit #942 C-141

Attachments:

Skelly Unit 975 C141 12.28.09.pdf; Skelly Unit 942 C-141 12.28.09.pdf

Please let me know if you need anything else.

Thank you,

Chasity Jackson COG OPERATING LLC 550 W. Texas Avenue, Suite 100 Midland, Texas 79701 p.432.686.3087 f.432.685.4396 **≫CONCHO** 

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

This inbound email has been scanned for malicious software and transmitted safely to you using Webroot Email Security.