

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1512454670

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production	Contact Brett Fulks
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-513-5819
Facility Name Cotton Draw 10 Fed 3H	Facility Type OIL

Surface Owner BLM	Mineral Owner BLM	API No. 30-015-42126
--------------------------	--------------------------	-----------------------------

LOCATION OF RELEASE

2RP-2983

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	10	25S	31E	200	North	1200	East	EDDY

Latitude: 32 deg 9'6.09" N Longitude: -103 deg 45'39.944"W

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release Unknown	Volume Recovered 0
Source of Release: Drilling Rigs (H&P 212)	Date and Hour of Occurrence 3/23/14-4/28/14	Date and Hour of Discovery April 2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

At some time during the drilling period of this well, a produced water spill must have occurred and was discovered by the environmental company hired by Devon for remediation on a different completions spill of 15 % Acid that occurred on 9/10/2015 (A separate C-141 was filed and closed for this incident).

Describe Area Affected and Cleanup Action Taken.*

The drilling Produced Water spill was estimated at 75' x 175' north of the wellheads. SESI was retained to assess and remediate the site in accordance with NMOCD guidelines. The impacted soils were removed to an NMOCD approved facility and the site restored to grade. SESI, on behalf of Devon respectfully requests closure of the regulatory file related to this incident.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Approved by Environmental Specialist: <i>MBratcher</i>	
Title: Field Admin Support	Approval Date: 1/11/2016	Expiration Date: N/A
E-mail Address: Denise.Menoud@dvn.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 12/14/2015 Phone: 575-746-5544	FINAL REPORT	

* Attach Additional Sheets If Necessary

2RP-2983