

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 3/29/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

n JMW 1217347760 JRP-1184 OPERATOR ☐ Initial Report ☒ Final Report

Name of Company	ALAMO PERMIAN RESOURCES, LLC	Contact	CARIE STOKER
Address	415 W. WALL ST. SUITE 500	Telephone No.	432 664 7659
Facility Name	EMPIRE J FEDERAL #3	Facility Type	

Surface Owner	FEDERAL	Mineral Owner	FEDERAL	API No.	30-015-00169
---------------	---------	---------------	---------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	1	18S	26E	2304	N	330	E	EDDY

Latitude 32.7723 Longitude -104.32915

NATURE OF RELEASE

Type of Release: Oil & Water	Volume of Release: EST 3 bbls oil; 11 bbls wtr	Volume Recovered: 2 bbls oil
Source of Release: Backside Casing Valve	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 6/14/12
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Stewart	
By Whom? Jennifer Van Curen	Date and Hour 6/14/12	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
Cause of problem: Discharge from backside casing valve Remedial Action Taken: Vacuum trucks dispatched to suck up standing fluid		
Describe Area Affected and Cleanup Action Taken.*		
Approximately 80 cubic yards of contaminated soil was removed and was transported to for proper disposal at Lea Land facility in New Mexico. The excavation backfilled with clean caliche material from Lea Land to bring the contours to surface grade. (see closure report for full details)		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <u>Carie Stoker</u>	OIL CONSERVATION DIVISION	
Printed Name: CARIE STOKER	Approved by Environmental Specialist:	
Title: REGULATORY/ PRODUCTION TECH	Approval Date: 4/1/2016	Expiration Date: N/A
E-mail Address: cstoker@helmsoil.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 03/23/2016	FINAL	
Phone: 432 664 7659		

* Attach Additional Sheets If Necessary

2RP-1184