

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 5/20/2016

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-432-685-4304
Facility Name: SRO STATE COM #018H	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner: State	API No. 30-015-39999
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	17	26S	28E	330'	North	330'	East	Eddy

Latitude 32.0488815 Longitude -104.1021042

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 10 bbls Oil ; 15 bbls PW	Volume Recovered: 8 bbls Oil ; 13 bbls PW
Source of Release: Dump valve	Date and Hour of Occurrence: 2/16/2016 7:00 am	Date and Hour of Discovery: 2/16/2016 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Robert Grubbs Jr.	Date and Hour: Wed 2/17/2016 8:06 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a hole in a dump valve on a FWKO. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. Concho will have the spill area evaluated for any possible contamination. The containment has been cleaned and the impacted gravel has been removed. Fresh gravel has been placed inside the containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 5/23/2016	Expiration Date: N/A
E-mail Address: rgrubbs@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 05-20-2016	Phone: 432-685-4304	

* Attach Additional Sheets If Necessary.

2RP-3575