

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 6/30/2016  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Sand Dunes 28 Federal #1 SWD Battery	Facility Type	SWD/Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-26194

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	28	23S	31E	1980'	South	1980'	East	Eddy County, NM

Latitude N 32.27385° Longitude W 103.78036°

#### NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	50 bbls	Volume Recovered	0 bbls
Source of Release	West Triplex pump was leaking	Date and Hour of Occurrence	10/01/2012	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; James Amos- BLM		
By Whom?	Chancey Summers, Oxy Permian	Date and Hour	10/22/2012 @ 10:55 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A leak on the west triplex pum caused 50 bbls of water to leak onto the ground. No fluids were recovered. The pump was repaired.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 3' x 200'. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 11/25//2015 and by Shelly Tucker of the BLM via email on 11/23/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Casey Summers	Approved by Environmental Specialist:		
Title: NM Environmental Advisor	Approval Date: 7/11/2016	Expiration Date: N/A	
E-mail Address: Casey.Summers@oxy.com	Conditions of Approval: FINAL		Attached <input type="checkbox"/>
Date: 6-29-16	Phone: (575) 513-8289		

\* Attach Additional Sheets If Necessary

2RP-1389