

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 8/2/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV BS #023H; 2RP#3192	Facility Type: Exploration and Production

Surface Owner: State	Mineral Owner:	API No. 30-015-41392
----------------------	----------------	----------------------

LOCATION OF RELEASE


Unit Letter N	Section 2	Township 25S	Range 30E	Feet from the 50	North/South Line South	Feet from the 1980	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	---------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: N 32.152604° Longitude: W 103.853799°

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 198 barrels	Volume Recovered: 150 barrels oil
Source of Release: Frac tank overflowed	Date and Hour of Occurrence: 8/4/15	Date and Hour of Discovery: 8/4/15 @ 7:47 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - Jim Amos	
By Whom? Bradley Blevins	Date and Hour: 8/4/15 @ 11:50 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* Well unloaded after well work was conducted causing the onsite frac tank to overflow to the ground surface.		
Describe Area Affected and Cleanup Action Taken.* Vacuum trucks were called to the location and recovered 150 barrels of oil. Samples were collected, and based on laboratory analytical data and NMOCD approval: the contaminated soil was excavated and hauled to a state approved disposal facility and the excavation backfilled with clean soil.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist:	
Printed Name: Bradley Blevins	Approval Date: 8/4/2016	Expiration Date: N/A
Title: Assistant Remediation Foreman	Conditions of Approval:	
E-mail Address: bblevins@basspet.com	Attached <input type="checkbox"/>	
Date: 7-26-16 Phone: 432-214-3704	FINAL	

* Attach Additional Sheets If Necessary

2RP-3192