

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 8/23/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	575-513-8289
Facility Name	Cedar Canyon 15 SWD #001	Facility Type	Battery

Surface Owner	Brantley- McDonald	Mineral Owner		API No.	30-015-42797
---------------	--------------------	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	15	24S	29E					Eddy

Latitude 32.21710 Longitude 103.97642

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	200 bbls	Volume Recovered	0 bbls
Source of Release	Failure of a transfer line clamp	Date and Hour of Occurrence	10/11/15	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Heather Patterson, Mike Bratcher		
By Whom?	Kathy Purvis @ BBC International	Date and Hour	10/13/15 11:45 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A transfer line clamp caused 200 bbls of produced water to leak on to the ground. No fluids were recovered and the clamp was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 100' x 250' on and off location. Remediation was completed in accordance with the remediation plan approved by Heather Patterson of NMOCD via email on 12/16/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Casey summers	Approved by Environmental Specialist:		
Title: NM Environmental Advisor	Approval Date: 8/26/2016	Expiration Date: N/A	
E-mail Address: : Casey_Summers@oxy.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>	
Date: 8-22-16 Phone: 575-513-8289			

* Attach Additional Sheets If Necessary

2RP-3384