

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company SM Energy Company	Contact Zach Luikens
Address 6301 Holiday Hill Rd, Bldg 1, Midland, TX 79707	Telephone No. (432) 688-3138
Facility Name Parkway 35 Federal Com 4H	Facility Type Well

Surface Owner: Federal	Mineral Owner	Lease No. API No. 30-015-39839
-------------------------------	---------------	---------------------------------------

LOCATION OF RELEASE

Unit Letter M	Section 35	Township 19S	Range 29E	Feet from the 450	North/South Line SOUTH	Feet from the 330	East/West Line WEST	County EDDY
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------

Latitude N 32.61488° Longitude W 104.05279°

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 15 bbls	Volume Recovered 15 bbls
Source of Release: 3" Polyethylene Line	Date and Hour of Occurrence 10/19/12 2:00 PM	Date and Hour of Discovery 10/19/12 2:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos & NMOCD voicemail	
By Whom? Bill Hearne	Date and Hour 10/19/12 4:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Talon LPE was working on an access road, lowering poly lines when the hit occurred. All standing fluid was recovered and the poly line was repaired.

Describe Area Affected and Cleanup Action Taken.*
Tetra Tech inspected site and collected samples to define spills extent. All samples collected were below laboratory reporting limits. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez	Approved by District Supervisor:	
Title: Project Manager	Approval Date: 8/29/2016	Expiration Date: N/A
E-mail Address: Ike.Tavarez@TetraTech.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 08/16/16 Phone: (432) 682-4559		

* Attach Additional Sheets If Necessary