

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 9/8/2016  
NMOCD Artesia  
Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Quick Draw 10 G #1	Facility Type: Producing Oil Well

Surface Owner: S& JW Properties LLC	Mineral Owner: Steve Willard	API No. 30-015-36500
-------------------------------------	------------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section 10	Township 20S	Range 25E	Feet from the 2310'	North/South Line North	Feet from the 1650'	East/West Line East	County Eddy
-------------	------------	--------------	-----------	---------------------	------------------------	---------------------	---------------------	-------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release: Oil Mist	Volume of Release: 10 bbls	Volume Recovered: 0 bbls
Source of Release: PRV	Date and Hour of Occurrence 8-19-13	Date and Hour of Discovery 8-19-13
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Cause- Back pressure valve on separator malfunctioned causing pressure relief valve to open and spray mist across the North and Northeast side.  
Remedial Action- Backed off pressure on separator then dumped fluid from separator to water tanks.

Describe Area Affected and Cleanup Action Taken.\*

Affected area- 200 ft to the North and 100 ft to the Northeast off the pad into the pasture (Mist). The pad was also affected around the separation equipment. Cleanup Action- Micro blaze misted area. Dug up and hauled off contaminated caliche from pad. Samples from the pad were taken on June 10, 2014 in connection with 2RP-2312 before backfilling.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Zack Thomas	Approved by Environmental Specialist:	
Title: Environmental Rep.	Approval Date: 9/8/2016	Expiration Date: N/A
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:  FINAL	Attached <input type="checkbox"/>
Date: 9-8-16 Phone: 575-602-2188		

\* Attach Additional Sheets If Necessary

2RP-1868