

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 9/12/2016

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report X Final Report

Name of Company: Burnett Oil Co., Inc.	Contact: Johnny Titsworth	
Address: Burnett Plaza-Ste 1500, 801 Cherry St-Unit 9, Fort Worth, TX 76102	Telephone No. (432) 425-2891	
Facility Name: Jackson B 44	Facility Type	
Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-34864

LOCATION OF RELEASE

Unit Letter C	Section 24	Township 17S	Range 30E	Feet from the 990	North/South Line FNL	Feet from the 2310	East/West Line FWL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: 32.82440 Longitude: -103.92677

NATURE OF RELEASE

Type of Release: oil/pw	Volume of Release: 3/5 bbls	Volume Recovered: 0/0
Source of Release: poly pipe	Date and Hour of Occurrence: 12/16/15 7:00am	Date and Hour of Discovery 12/16/15 7:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM – S. Tucker OCD – H. Patterson	
By Whom? Leslie Garvis	Date and Hour: 12/16/15 10:20 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A


Describe Cause of Problem and Remedial Action Taken.*

Weld on poly pipe gave way. Repair made and line was put back into service. Impacted area was sampled, tilled, and reseeded.

Describe Area Affected and Cleanup Action Taken.*

Affected area is approx. 75'x15' area in the pasture & 50'x100' overspray area on the well pad. The pad area was scrapped with a backhoe, and impacted soil was hauled to disposal. The pasture area was sampled, tilled, and reseeded. Area will be monitored for regrowth.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Johnny Titsworth	Approved by Environmental Specialist:		
Title: HSE Coordinator	Approval Date: 9/16/2016	Expiration Date: N/A	
E-mail Address: jtitsworth@burnettoil.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 8/12/16	Phone: (432) 425-2891		FINAL

* Attach Additional Sheets If Necessary

2RP-3455