

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nAB1628632716

#### OPERATOR

Initial Report  Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: SCREWDRIVER 24 FEDERAL COM #002H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42914
------------------------	------------------------	----------------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	24	19S	31E	900'	South	190'	East	Eddy

Latitude 32.641211617 Longitude -103.83072596

#### NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 22 bbls Oil	Volume Recovered: 21 bbls Oil
Source of Release: Broken Sight Glass	Date and Hour of Occurrence: 10/5/2016 7:00 am	Date and Hour of Discovery: 10/5/2016 7:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by a broken sight glass. The sight glass has been replaced and a protective cover placed on the sight glass.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred within the lined facility and a light mist went onto the location. A vacuum truck was dispatched to recover standing fluid and the facility and equipment were pressure washed. The small area of the location impacted by the mist was scraped up and hauled off to an appropriate disposal facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Dakota Neel	Approved by Environmental Specialist: <i>MBratcher</i>	
Title: Environmental Coordinator	Approval Date: 11/30/16	Expiration Date: N/A
E-mail Address: dneel2@concho.com	Conditions of Approval: BLM approval	Attached <input type="checkbox"/>
Date: November 4, 2016 Phone: 575-748-6933	FINAL	

\* Attach Additional Sheets If Necessary.

2RP-3935