

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 11/3/2016

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: SUPERFORTRESS 29 FEDERAL #003H	Facility Type: Battery	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-38642

LOCATION OF RELEASE

Unit Letter C	Section 29	Township 19S	Range 31E	Feet from the 330	North/South Line North	Feet from the 2200	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

32.6377373,-103.8928909

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 10 bbls Produced Water	Volume Recovered: 7 bbls Produced Water
Source of Release:	Date and Hour of Occurrence: 9/30/2016 unknown	Date and Hour of Discovery: 9/30/2016 12:01 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a hole in a check valve. The damaged check valve was replaced to prevent the incident from occurring again.

Describe Area Affected and Cleanup Action Taken.*

This battery occurred within a lined facility. Vacuum trucks were immediately dispatched to recover all standing fluid. The contaminated gravel was removed and the liner and equipment were pressure washed before fresh gravel was placed back on the liner.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel	Approved by Environmental Specialist:	
Title: Environmental Coordinator	Approval Date: 12/1/2016	Expiration Date: N/A
E-mail Address: dneel2@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: November 3, 2016	Phone: 575-748-6933	

* Attach Additional Sheets If Necessary

2RP-3933