

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 11/23/2016  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: ADMIRAL FEDERAL COM #002H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42820
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	28	25S	29E	190	South	1980	East	Eddy

**32.0940460962434,-103.9871068537**

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release: 355 bbls of Oil	Volume Recovered: 350 bbls of Oil
Source of Release: Valve	Date and Hour of Occurrence: 10/18/2016 7:00 AM	Date and Hour of Discovery: 10/18/2016 8:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD/ Shelly Tucker BLM	
By Whom? Dakota Neel	Date and Hour: 10/20/2016 1:49 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The release was caused by an equalizer valve being in the wrong position. The valve was placed back in the correct position. Vacuum trucks were immediately dispatched to recover all standing fluids.

Describe Area Affected and Cleanup Action Taken.\*

This release was contained within the falcon lined facility. Free standing fluids were removed via vacuum truck and the facility was pressure washed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Dakota Neel	Approved by Environmental Specialist:	
Title: Environmental Coordinator	Approval Date: 12/1/2016	Expiration Date: N/A
E-mail Address: dneel2@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: November 21, 2016, 2016 Phone: 575-748-6933	FINAL	

\* Attach Additional Sheets If Necessary

1RP-3962