

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 12/7/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Matador Resources Company	Contact Catherine Green
Address 500 n Main St Ste One Roswell NM 88201	Telephone No. 575-623-6601
Facility Name Charlie Sweeney 201 H	Facility Type Production Battery

Surface Owner Fee	Mineral Owner	API No. 30-015-43695
-------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	30	23S	28E	492	South	497	West	Eddy

Latitude 32.2700693 Longitude 104.133231

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 25bbls	Volume Recovered 10bblsValv
Source of Release Valve not closed properly	Date and Hour of Occurrence 9/20/2016 6am	Date and Hour of Discovery 9/20/2016 6am
Was Immediate Notice Given? Required <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Catherine Green	
By Whom? Heith Gaspard	Date and Hour 9/20/2016 10am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Water hauler did not properly close load valve. Lease operator discovered open valve, closed it, and called for vacuum truck to vacuum up excess fluid on production pad.

Describe Area Affected and Cleanup Action Taken.*

Produced water spilled on ground around load line. Soil will be sampled for contamination. Contaminated soil will be removed and replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Catherine Green</i>	OIL CONSERVATION DIVISION	
Printed Name: Catherine Green	Approved by Environmental Specialist: <i>Heather Patterson</i>	
Title: Regulatory Analyst	Approval Date: 12/12/2016	Expiration Date: N/A
E-mail Address: cgreen@matadorresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/07/2016 Phone: 575-627-2453	FINAL	

* Attach Additional Sheets If Necessary