

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
 accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1633649257

OPERATOR

Initial Report Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	Dirty Dozen 4H Battery	Facility Type:	Tank Battery

Surface Owner:	Federal	Mineral Owner:		API No.	30-015-38150
----------------	---------	----------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	36	19S	31E	1650	South	660	East	Eddy

Latitude 32.614254 Longitude 103.8162079

NATURE OF RELEASE

Type of Release:	Oil	Volume of Release:	75 bbls	Volume Recovered:	72 bbls
Source of Release:	Tank	Date and Hour of Occurrence:	11/24/2016 10:00 am	Date and Hour of Discovery:	11/24/2016 10:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Ms. Patterson - NMOCD / Ms. Tucker - BLM		
By Whom?	Rebecca Haskell	Date and Hour:	Thursday, 11/24/2016 3:32 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A valve was in the incorrect position causing the tank to overflow. The valve was switched to the correct position.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment has been cleaned.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	OIL CONSERVATION DIVISION		
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>[Signature]</i>		
Title: Senior HSE Coordinator	Approval Date: 1/26/17	Expiration Date: N/A	
E-mail Address: rhaskell@concho.com	Conditions of Approval: Like approval BLM Battery cleaned		Attached <input type="checkbox"/>
Date: January 26, 2017 Phone: 432-683-7443	FINAL		

* Attach Additional Sheets If Necessary

2RP-4013