

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

NMOCD Dist 2

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nAB1500828256

**OPERATOR**

Initial Report  Final Report

Name of Company EOG Y Resources, Inc.	Contact Amber Griffin
Address 104 S. 4 <sup>th</sup> Street	Telephone No. 575-748-1471
Facility Name Compromise SWD #1	Facility Type Salt Water Disposal Battery

Surface Owner Fee	Mineral Owner BOR	API No. 30-015-25665
----------------------	----------------------	-------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	30	18S	27E	1980	North	800	East	Eddy

Latitude 32.72051 Longitude 104.31146

**NATURE OF RELEASE**

Type of Release Produced water	Volume of Release 200 B/PW	Volume Recovered 175 B/PW
Source of Release Produced water tank	Date and Hour of Occurrence 12/31/2014; AM	Date and Hour of Discovery 12/31/2014; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Bob Asher/Yates Petroleum Corporation	Date and Hour 1/5/2015 (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

The motor burned out on the produced water tank and it overflowed. Wells were shut off and vacuum truck(s) and roustabout crew were called.

Describe Area Affected and Cleanup Action Taken.\*

The area affected was within the unlined, bermed battery (dimensions are unknown at this time). The wells were shut off and problems with the motor were corrected. Vacuum truck removed standing fluid (175 B/PW). Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 20) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. **Depth to Ground Water: < 50' (approximately 35'), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20. Yates requests closure as all work has been completed as per the previously NMOCD approved work plan.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amber Griffin	Approved by Environmental Specialist: 	
Title: Rep Safety & Environmental II	Approval Date: 1/31/17	Expiration Date: N/A
E-mail Address: <a href="mailto:amber_griffin@egoresources.com">amber_griffin@egoresources.com</a>	Conditions of Approval: N/A FINAL	Attached <input type="checkbox"/>
Date: January 6, 2017	Phone: 575-748-4111	2RP-2717

\* Attach Additional Sheets If Necessary

2RP-2717