

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 1/30/2017

NMOCD Dist 2

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1601227198

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: GRAVE DIGGER STATE COM #008H	Facility Type: Well

Surface Owner: Fee	Mineral Owner: State	API No. 30-015-43397
--------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	2	20S	25E	170'	South	1610'	West	Eddy

Latitude 32.5956523 Longitude -104.45835101

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 19 bbls PW	Volume Recovered: unknown
Source of Release: Frac Tank Valve	Date and Hour of Occurrence: 12/21/2015 12:00 am	Date and Hour of Discovery: 12/21/2015 6:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A leak from the frac tank valve was discovered on the backside of the tank.

Describe Area Affected and Cleanup Action Taken.*

The release ran off the backside of the location into the pasture. This release occurred on fee surface and was caused by a third party working on location. Concho had the spill site sampled to delineate any possible contamination from the release and remediated the site in accordance to the workplan submitted to and approved by the NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel		Approved by Environmental Specialist: 	
Title: Environmental Coordinator	Approval Date: 2/22/17	Expiration Date: N/A	
E-mail Address: dneel2@concho.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: 12/28/2016	Phone: 575-748-6933		

* Attach Additional Sheets If Necessary

2RP-3488