

DEFERRAL

Received 6/21/2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NMOCD Dist 2

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**DEFERRAL**

nAB1607042880

OPERATOR☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Cypress 34 Federal #1CTB	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	API No. 30-015-35053

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	34	23S	29E	460	South	660	East	Eddy

Latitude N 32.25508° Longitude W 103.96647°**NATURE OF RELEASE**

Type of Release	Oil and produced water	Volume of Release	10 bbls oil, 10 bbls produced water	Volume Recovered	15 bbls
Source of Release	A dump line clog forced fluids to spill out of the test heater	Date and Hour of Occurrence	02/28/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Kathy @BBC International.com	Date and Hour	03/02/2016 @ 11:37 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A dump line clog forced 10 bbls of oil and 10 bbls of produced water to spill out of the test heater. A vacuum truck recovered 15 bbls of fluids and the dump line was unclogged.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 90' x 45' on location inside containment. Remediation was completed in accordance with a remediation plan approved by Mike Bratcher of NMOCD via email on 05/13/2016 and by Shelly Tucker of the BLM via personal meeting.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Casey Summers

Title: NM Environmental Advisor

E-mail Address: Casey.Summers@oxy.com

Date: 6-13-16 Phone: (575) 513-8289

Approved by Environmental Specialist: Accepted for Record/Deferral

Approval Date: DEFERRAL

Expiration Date:

Conditions of Approval:
REMEDATION IS DEFERRED
UNTIL CONTAMINATED AREA
IS ACCESSIBLE

Attached ☐

* Attach Additional Sheets If Necessary

2RP-3608