

State of New Mexico
Energy Minerals and Natural Resources

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1619757075

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-230-0077
Facility Name: VT 36 State #001H	Facility Type: Flow line

Surface Owner: State	Mineral Owner:	API No. 30-015-37690
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	36	19S	25E	480	North	330	West	Eddy County, NM

Latitude N 32.62279° Longitude W 104.44295°

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 40 bbls	Volume Recovered: 0 bbls
Source of Release: 4" Balon valve	Date and Hour of Occurrence: 07/06/2016 @ 8:00 am	Date and Hour of Discovery: 07/06/2016 @ 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher- NMOCD, Amber Groves- SLO	
By Whom? Robert Grubbs Jr.	Date and Hour: 07/12/2016 @ 1:36 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


A 4" Balon valve corroded due to age. The valve was replaced with a new one.

Describe Area Affected and Cleanup Action Taken.*

This release impacted a 200' x 80' area in the pasture. The site was delineated and a remediation plan was sent to NMOCD and the SLO. The remediation plan was approved by Mike Bratcher of NMOCD via email on 12/15/2016 and approved by Amber Groves of the SLO via email on 12/21/2016. Remediation was completed in accordance with the approved plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Robert Grubbs Jr	Approval Date: 5/11/17	Expiration Date: N/A
Title: Senior Environmental Coordinator	Conditions of Approval: N/A	
E-mail Address: rgrubbs@concho.com	FINAL	Attached <input type="checkbox"/>
Date: January 3, 2017	Phone: (432) 683-7443	

* Attach Additional Sheets If Necessary

2RP-3781