

Received 6/21/2017
NMOCD Dist 2

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1715757481

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Diamondback 22 State Com #003H	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner:	API No. 30-015-39861
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 22	Township 26S	Range 28E	Feet from the 550	North/South Line North	Feet from the 660	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.0337791 Longitude -104.0685806

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 12 bbls	Volume Recovered: 10 bbls
Source of Release: Water line	Date and Hour of Occurrence: May 27, 2017 11:00 am	Date and Hour of Discovery: May 27, 2017 11:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The release was due to a hole in a steel water line going to the tanks. The water line was replaced.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment has been cleaned and the impacted gravel has been removed. Fresh gravel has been placed inside the containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Haskell	<i>[Signature]</i>	
Title: Senior HSE Coordinator	Approved by Environmental Specialist:	
E-mail Address: rhaskell@concho.com	Approval Date: 9/14/17	Expiration Date: N/A
Date: June 21, 2017 Phone: 432-683-7443	Conditions of Approval: N/A FINAL	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-4242