

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OCD  
District II Artesia  
Closed 9/21/17  
Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Buena Vista 2 State Com #002H	Facility Type: Tank Battery
Surface Owner: Private	Mineral Owner: State
API No. 30-015-41290	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	02	20S	30E	480	South	2,030	East	Eddy

Latitude 32.5963554 Longitude -103.9409256

#### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 25 bbl.	Volume Recovered: 20 bbl.
Source of Release: Water Line	Date and Hour of Occurrence: September 1, 2017 9:00 am	Date and Hour of Discovery: September 1, 2017 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Weaver - NMOCD / Ms. Groves	
By Whom? Rebecca Haskell	Date and Hour: September 1, 2017 Time of this Email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

The release was due to a pin hole leak on a four-inch check valve on the FWKO water line. The four-inch check valve was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho has had the free fluids and any impacted material inside the lined facility removed. The liner has been cleaned and the facility is back in operation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Dakota Neel	Approved by Environmental Specialist: 	
Title: HSE Coordinator	Approval Date: 9/21/17	Expiration Date: N/A
E-mail Address: dneel2@concho.com	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: September 19, 2017 Phone: 575-746-2010		

\* Attach Additional Sheets If Necessary

**2RP-4369**