

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1724035823

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Production LLC OGRID # 217955	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: Copperhead Fee A #001H	Facility Type: Tank Battery	
Surface Owner: Private	Mineral Owner: Private	API No. 30-015-38227

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	31	26S	29E	480	South	480	West	Eddy

Latitude 32.0014076 Longitude -104.0308685

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 20 bbl. Oil & 110 bbl. PW	Volume Recovered: 18 bbl. Oil & 105 bbl. PW
Source of Release: Nipple	Date and Hour of Occurrence: August 22, 2017 6:00 am	Date and Hour of Discovery: August 22, 2017 6:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Weaver – NMOCD	
By Whom? Rebecca Haskell	Date and Hour: August 22, 2017 2:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The release was due to corrosion to a nipple located before the isolation valve.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids and the containment was pressure washed to remove any residue from the release. The lined containment was inspected and found to be structurally sound.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel		Approved by Environmental Specialist: 	
Title: HSE Coordinator		Approval Date: 10/24/17	Expiration Date: N/A
E-mail Address: dneel2@concho.com		Conditions of Approval: N/A	
Date: October 4, 2017 Phone: 575-746-2010		Attached <input type="checkbox"/>	
		FINAL	

* Attach Additional Sheets If Necessary

2RP-4360