

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised April 3, 2017

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action** Remediation Deferred - Open

nAB1606240430

**OPERATOR**

Initial Report  Final Report

Name of Company: <b>COG Operating, LLC (OGRID# 229137)</b>	Contact: <b>Robert McNeill</b>
Address: <b>600 West Illinois Avenue, Midland TX 79701</b>	Telephone No.: <b>432-683-7443</b>
Facility Name: <b>Foster Eddy #011</b>	Facility Type: <b>Well</b>

Surface Owner: <b>BLM</b>	Mineral Owner: <b>Federal</b>	API No.: <b>30-015-26231</b>
---------------------------	-------------------------------	------------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	17	17S	31E	1650	South	2160	East	Eddy

Latitude: 32.8318329 Longitude: -103.8903885 NAD83

**NATURE OF RELEASE**

Type of Release: <b>Oil &amp; Produced Water</b>	Volume of Release: <b>3bbls Oil &amp; 2bbls PW</b>	Volume Recovered: <b>2bbls Oil &amp; 1bbl PW</b>
Source of Release: <b>Flowline</b>	Date and Hour of Occurrence: <b>2/2/2016 1:00pm</b>	Date and Hour of Discovery: <b>2/12/2016 1:00pm</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A poly flowline ruptured resulting in the release of approximately 3bbls of oil and 2bbls of produced water. A vacuum truck was dispatched to the site to recover freestanding fluids. Approximately 2bbls of oil and 1bbl of produced water were recovered.

Describe Area Affected and Cleanup Action Taken.\*  
The release occurred in the pasture approximately 275-feet northeast of the wellhead. Concho conducted soil sampling within the impacted area and developed a remediation work plan that was subsequently approved by NMOCD and BLM. The soil remediation at this site was carried out per the approved work plan. Excavation limitations were encountered due to underground pipelines intersecting the impacted area. A deferment request was submitted to NMOCD and BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>	
	<b>ACCEPTED FOR DEFERRMENT ONLY</b>	
Printed Name: Sheldon L. Hitchcock	Approved by Environmental Specialist:	
Title: HSE Coordinator	Approval Date: 10/30/17	Expiration Date: N/A
E-mail Address: slhitchcock@concho.com	Conditions of Approval: Like Approval BLM	Attached <input type="checkbox"/>
Date: 10/6/2017 Phone: 575-746-2010	Accepted for deferrment only	

\* Attach Additional Sheets If Necessary