

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received on
11/3/17
OCD DII
Artesia, NM

Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Loco Hills SWD 33 #004	Facility Type: SWD

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-37269
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 33	Township 17S	Range 30E	Feet from the 840	North/South Line South	Feet from the 660	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.7860756 Longitude -103.9705276

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 100 bbl. Oil & 600 bbl. Pw	Volume Recovered: 95 bbl. Oil & 590 Produced Water
Source of Release: Lightning Strike	Date and Hour of Occurrence: August 21, 2017 2:00 am	Date and Hour of Discovery: August 21, 2017 2:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Weaver - NMOCD / Ms. Tucker - BLM	
By Whom? Dakota Neel	Date and Hour: August 21, 2017 4:57 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The release occurred when lightning struck the facility. The facility and equipment were a total loss.

Describe Area Affected and Cleanup Action Taken.*

The release remained within the bermed area. A vacuum truck was dispatched to remove all freestanding fluids. The site was delineated according to OCD standards and a remediation plan was prepared. Remediation was completed in accordance with the remediation plan approved by the NMOCD and BLM via email on September 29, 2017.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>Crystal W.</i>	
Title: Senior HSE Coordinator	Approval Date: 12/5/17	Expiration Date: N/A
E-mail Address: rhaskell@concho.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: November 3, 2017 Phone: 432-683-7443		

* Attach Additional Sheets If Necessary

2RP-4359