

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Marathon Oil Permian LLC	Contact Callie Karrigan
Address 5555 San Felipe Street, Houston, Texas 77056	Telephone No. 405-202-1028 (cell) 575-297-0956 (office)
Facility Name: Cypress #5	Facility Type Oil and gas production facilities

Surface: Owner: Fee	Mineral: Owner: Fee	API No.: 30-015-36313
---------------------	---------------------	-----------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	9	23S	27E	660	South	660	West	Eddy

Latitude 32.313875N Longitude -104.201094W

### NATURE OF RELEASE


Type of Release: oil	Volume of Release: 5 gallons	Volume Recovered: 0
Source of Release: flare	Date and Hour of Occurrence 04/11/2018 9:30 am	Date and Hour of Discovery 04/11/2018 9:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Crystal Weaver and Mike Bratcher – Eddy County	
By Whom? Callie Karrigan	Date and Hour 04/11/2018 5:02 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
Not applicable.

Describe Cause of Problem and Remedial Action Taken.\*  
While performing a tank switch, onsite Flowback Operator did not verify that a secondary production valve was closed. This resulted in oil from the heater treater to high level and release fluids to the flare gas scrubber, filling the scrubber and releasing from the flare stack. Approximately 5 gallons of oil was released from the flare stack, igniting a small fire around the base of the flare stack. Overspray traveled approximately 160 feet.

Describe Area Affected and Cleanup Action Taken.\*  
Affected material was removed from the well pad. Site was remediated as per attached closure report.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Callie Karrigan</i>	<u>OIL CONSERVATION DIVISION</u> 	
Printed Name: Callie Karrigan		
Title: HES Environmental Professional	Approved by Environmental Specialist:	Approval Date: 08/20/18
E-mail Address: cnkarrigan@marathonoil.com	Expiration Date: N/A	Conditions of Approval:
Date: 8/17/18 Phone: 405-202-1028 (cell) 575-297-0956 (office)	N/A	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2RP-4720

**FINAL**