

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	OXY USA INC	Contact	WADE DITTRICH
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-390-2828
Facility Name	HARROUN 9-1 CTB	Facility Type	CTB

Surface Owner	PRIVATE	Mineral Owner	STATE	API No.	30-015-34894
---------------	---------	---------------	-------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	9	24S	29E	530	SOUTH	330	EAST	EDDY

Latitude 32.2262 Longitude -103.98184 NAD83

NATURE OF RELEASE

Type of Release	OIL & PRODUCED WATER	Volume of Release	10 BBLS OIL 110 BBLS PRODUCED WATER	Volume Recovered	119 BBLS
Source of Release	HOLE IN BOTTOM OF TANK	Date and Hour of Occurrence	11/4/2017	Date and Hour of Discovery	11/6/2017
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER-NMOCD; CRYSTAL WEAVER-NMOCD			
By Whom?	WADE DITTRICH	Date and Hour 11/6/2017 @ 9:28 AM			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Hole in bottom of tank. The issue was corrected and returned to service.
LOCATION SITE WAS REMEDIATED

Describe Area Affected and Cleanup Action Taken.*

Affected area of the spill is approximately 50x100 ft (measurements are subject to change with GPS tracking). Remediation was completed in accordance with a remediation plan approved by the NMOCD and the BLM. The RP number for this event is 2RP-4493

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: WADE DITTRICH	Approved by Environmental Specialist: 	
Title: ENVIROMENTAL COORDINATOR	Approval Date: 08/22/18	Expiration Date: N/A
E-mail Address: wade_dittrich@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8-06-2018 Phone: 575-390-2828	N/A	

* Attach Additional Sheets If Necessary

FINAL 2RP-4493