

Submit 1 Copy To Appropriate District  
Office  
District I – (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II – (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III – (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV – (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-00991
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Injection <input type="checkbox"/>		5. Indicate Type of Lease STATE X FEE
2. Name of Operator State of New Mexico for Canyon E&P Company		6. State Oil & Gas Lease No.
3. Address of Operator 811 S. First Street Artesia, NM 88210		7. Lease Name or Unit Agreement Name Artesia Metex Unit
4. Well Location Unit Letter C : 330 feet from the North line and 2310 feet from the West line Section 36 Township 18S Range 27E NMPM Eddy County		8. Well Number 058
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 269864
		10. Pool name or Wildcat Artesia QU-GB-SA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/> OTHER: <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A XX CASING/CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>
---	---

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

**SEE ATTACHED**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Type or print name \_\_\_\_\_ E-mail address: \_\_\_\_\_ PHONE: \_\_\_\_\_  
**For State Use Only**

APPROVED BY: Gilbert Cordero TITLE Staff MGR DATE 4/9/20  
Conditions of Approval (if any):

Plugging Report  
Artesia Metex Unit #58  
API 30-015-00991

3/17/2020      Cleared location. Moved in rig and rigged up. Tubing was parted just below the wellhead. Tagged fish with wireline at 100'. RIH with workstring and spear and caught fish. Worked pipe free and started laying down the tubing that was in the well. SION

3/18/2020      Finished laying down tubing. Set 4 ½" CIBP at 1752'. Circulated MLF and tested casing to 500#. Casing good. Spot 35 sx Class C cement on top of CIBP. POOH and perforated casing at 485'. Pressured up on perfs to 500# and held with no drop. Bumped the pressure up to 700# and held. Bled off at the truck and pressured up again to 700#. Repeated the process with same result. RIH with tubing to 539' and circulated cement to surface with 40 sx. Laid down remaining pipe and rigged down.

3/19/2020      Dug out and cut off wellhead. Cement had fallen considerably inside the 4 ½" casing and there was no cement or fluid inside the annulus between the 4 ½" and 8 5/8" casing. Filled up the 4 ½" casing with 15 sx and the annulus with 40 sx. Cement remained at surface in both strings of casing. Installed marker, removed anchors, cleaned the pit and cleared the location.