Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Rec'd 06/12/2020 - NMOCD FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Lease Serial No. NMNM132070

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals

abanaonoa no	000 101 0100 0 (1	z) rer eden propeedier				
SUBMIT IN	7. If Uni	7. If Unit or CA/Agreement, Name and/or No.				
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Oth		8. Well Name and No. SD EA 18 19 FED COM P15 17H				
2. Name of Operator CHEVRON USA INCORPORA		9. API Well No. 30-025-44089-00-X1				
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706		3b. Phone No. (include area code) Ph: 432-687-7655		10. Field and Pool or Exploratory Area WC025G09S263327G-UP WOLFCAMP		
4. Location of Well (Footage, Sec., T Sec 18 T26S R33E NENE 45: 32.049538 N Lat, 103.605919		11. County or Parish, State LEA COUNTY, NM				
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPOR	T, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
	☐ Acidize ☐ Alter Casing ☐ Casing Repair	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete		☐ Water Shut-Off ☐ Well Integrity ☐ Other	
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☐ Plug and Abandon ☐ Plug Back	☐ Temporarily Abandon ☐ Water Disposal		3 ss	
13. Describe Proposed or Completed Op If the proposal is to deepen direction: Attach the Bond under which the wo following completion of the involved	ally or recomplete horizontally, rk will be performed or provide	give subsurface locations and measu the Bond No. on file with BLM/BIA	red and true vertical deptl Required subsequent re	ns of all pertino ports must be	ent markers and zones. filed within 30 days	

testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has

Chevron USA requests authorization to temporarily abandon this well by pulling the 5-1/2" RBP and setting a 5-1/2" CIBP. Wellbore status and detailed program below.

WELL STATUS: Well suspended with RBP set at 11,947'. Squeezed perforations at 12,160'-12,165'. RSI sleeve isolated with a 5" 15K rated Copperhead bridge plug set at 22,403' MD. LDS Tubing Hanger w/ BPV and 10 ppg packer fluid currently in wellbore.

PROGRAM:

determined that the site is ready for final inspection.

- MIRU. N/D night cap. N/U LMV. Pull tubing hanger.
 MIRU braided line unit & test lubricator. RIH and pull Peak 5-1/2" RBP @ 11,947'. POOH.
 MIRU e-line unit & test lubricator. RIH with 5-1/2" CIBP and set at ~12,080' (top squeeze perf at 12,160').

14. I hereby certify that the foregoing is true and correct. Electronic Submission #513828 verified by the BLM Well Information System For CHEVRON USA INCORPORATED, sent to the Hobbs Committed to AFMSS for processing by PRISCILLA PEREZ on 05/04/2020 (20PP2472SE)							
Name(Printed/Typed)	LAURA BECERRA	Title	REGULATORY SPECIALIST				
Signature	(Electronic Submission)	Date	05/04/2020				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
_Approved By NDUNGU KAMAU		TitleF	ETROLEUM ENGINEER	Date 05/15/2020			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Hobbs				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #513828 that would not fit on the form

32. Additional remarks, continued

- 4. RIH and dump bail 35' cement on top of CIBP. Tag TOC, ensuring at least 35' of cement on top of CIBP.
 5. Perform official MIT to 500 psi for 30 minutes, on chart.
 Notify BLM per COA prior to test.
 6. RDMO Wireline. Install BPV in 5-1/2" casing hanger profile
 7. N/D frac valve & install night cap. RDMO

Revisions to Operator-Submitted EC Data for Sundry Notice #513828

Operator Submitted BLM Revised (AFMSS)

TA NOI TA NOI Sundry Type:

NMNM132070 NMNM132070 Lease:

Agreement:

Operator: CHEVRON USA INC CHEVRON USA INCORPORATED

6301 DEAUVILLE BLVD MIDLAND, TX 79706 6301 DEAUVILLE BLVD MIDLAND, TX 79706 Ph: 432.687.7100 Fx: 432-687-7221 Ph: 432-687-7665

Admin Contact:

LAURA BECERRA REGULATORY SPECIALIST E-Mail: LBECERRA@CHEVRON.COM LAURA BECERRA REGULATORY SPECIALIST E-Mail: LBECERRA@CHEVRON.COM

Ph: 432-687-7665 Ph: 432-687-7655

Tech Contact:

LAURA BECERRA REGULATORY SPECIALIST

LAURA BECERRA REGULATORY SPECIALIST E-Mail: LBECERRA@CHEVRON.COM E-Mail: LBECERRA@CHEVRON.COM

Ph: 432-687-7665 Ph: 432-687-7655

Location:

State: County: NM EDDY NM LEA

SANDERS TANK; UPR WOLFCAMP WC025G09S263327G-UP WOLFCAMP Field/Pool:

Well/Facility: SD EA 18 19 FED COM P15 17H

SD EA 18 19 FED COM P15 17H Sec 18 T26S R33E NENE 455FNL 955FEL Sec 18 T26S R33E Mer NMP NENE 455FNL 955FEL 32.049538 N Lat, 103.605919 W Lon

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval for Temporary Abandonment of Wells

Definition: A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

- 1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
- 2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
 - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
 - b. A description of the temporary abandonment procedure.
 - c. A clear copy or the original of the pressure test chart.