

District II – Artesia811 S. 1st Street, Artesia, NM 88210

Phone: (575) 748-1283 - Fax: (575) 748-9720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name OXY	* API Number 30-015-38254
Property Name Lost Tank 3 Federal	Well No. 025

1. Surface Location

UL - Lot H	Section 3	Township 22S	Range 31E	Feet from 1500	WS Line 0	Feet From 541	DW Line 0	County Eddy
----------------------	---------------------	------------------------	---------------------	--------------------------	---------------------	-------------------------	---------------------	-----------------------

Well Status

TA'D Well		SHUT-IN		INJECTOR		PRODUCER		DATE
YES	NO	YES	NO	INJ	SWD	OIL	GAS	10-7-20

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0	0		0	1350
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO ₂ _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

A - Puff Gas
B - Puff Gas
D - Puff Water

Accepted for record
NMOCD DS 3-9-2021

Signature: _____		OIL CONSERVATION DIVISION	
Printed name: Reggie House		Entered _____	
Title: Production Tech II		Re-test _____	
E-mail Address: reggie.house@oxy.com			
Date: 10-7-20	Phone: 575-942-0363		
Signature: Reggie House	Witness: _____		