

2901 Via Fortuna Suite 600 • Austin, Texas 78746 • Phone (737) 300-4700

April 7, 2022 (revised August 23, 2022)

NMOCD – District 1 Hobbs C/O Barbara Lydick 1625 N. French Drive Hobbs, NM 88240

RE: Compliance Notice Response - Revised

Compliance #: cBZL227526830 AEP #: 20220307-1300-prodops

Location: Herkimer BQF Fed #1H (API #: 30-025-20381)

Ms. Lydick,

Ameredev II performed compliance corrective actions on March 28-29, 2022 and the removal of the tank battery, associated impacted material, and containment on August 15-16, 2022. This revision includes the restoration of the tank battery area. Ameredev II respectfully asks NMOCD for closure of the compliance notice.

Wellhead Cellar

The wellhead was power-washed and the wellhead cellar impacted material was excavated to a depth of 1.5 ft. Impacted material was hauled to an NMOCD approved disposal facility. The wellhead cellar was backfilled with clean pea gravel.



Photo of compliance action from NMOCD



Completed compliance action. March 28-29, 2022

Compliance #: cBZL227526830 AEP #: 20220307-1300-prodops Herkimer BQF Fed #1H

Pump Jack Area

The production pad around the pump jack was surface scraped. Impacted material was hauled to an NMOCD approved disposal facility. The surface was restored with clean caliche.




Photo of compliance action from NMOCD



Completed compliance action. March 28-29, 2022

Area outside of tank battery containment at pumpkin

The production pad around tank battery disposal line pumpkin was surface scraped. Impacted material was hauled to an NMOCD approved disposal facility. The surface was restored with clean caliche.



Photo of compliance action from NMOCD



Completed compliance action. March 28-29, 2022



Compliance #: cBZL227526830 AEP #: 20220307-1300-prodops Herkimer BQF Fed #1H

Area around the tank battery and within the containment

Ameredev II removed the tank battery, liner, and containment walls; and hauled impacted material off-site to an approved disposal facility. The surface was restored to an active production pad.



Photo of compliance action from NMOCD



Photo of compliance action during Ameredev field inspection on 03/18/2022.



Photograph of former tank battery and containment area. The area of interest was restored to an active production pad. Photo is viewing west-southwest from the Herkimer wellhead. (August 16, 2022)



Compliance #: cBZL227526830 AEP #: 20220307-1300-prodops Herkimer BQF Fed #1H

Please contact me with any questions.

Sincerely,

Andrew Parker Environmental Scientist Ameredev II (aka Ameredev Operation)

Cc: Dayeed Kahn, Ameredev Operating

