


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NMLB1129354803

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: LINN Energy	Contact: Joe Hernandez
Address: 2130 W Bender Blvd. - Hobbs, NM	Telephone No.: 575-942-8675
Facility Name: JL Keel A #14	Facility Type: Injection Well

Surface Owner: BLM	Mineral Owner: BLM	Lease No.: 3001505102
--------------------	--------------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	7	17S	31E	660	N	579	W	Eddy

Latitude: 32 51' 15.993" Longitude: -103 54' 54.200"

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 77	Volume Recovered: 0
Source of Release: Injection Line Leak	Date and Hour of Occurrence: 10/6/11 - Unknown	Date and Hour of Discovery: 10/6/11 - 1600
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? T. Gregston, BLM- Mike Bratcher NMOC D	<i>No Record of Notification to OCD</i>
By Whom? J. Hernandez	Date and Hour: 10/7/11-0900	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Line leak from fitting failiuer on burried line. Exposed and repaired line.

Describe Area Affected and Cleanup Action Taken.*: Area is approxiamtely 250 yds NE of the Keel A # 14. Estiamted surface area is 19,000 sq. ft. Further assessment and corrective action plan pending.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>[Signature]</i>	Signed By <i>[Signature]</i>	
Printed Name: Jose Hernandez	Approved by District Supervisor: <i>[Signature]</i>	
Title: Foreman	Approval Date: OCT 20 2011	Expiration Date:
E-mail Address: jhernandez@linneenrgy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: J. Hernandez Phone: 575-738-1739	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 11/20/2011	

* Attach Additional Sheets If Necessary

2RP-929